



कार्यालय नगर निगम मथुरा-वृन्दावन, मथुरा

पत्रांक : 21 / नि0वि0का0 / न0नि0म0वृ0, वृन्दावन-जोन / 2025-26

दिनांक: 09/02/2026

Building Safety Certificate

Certificate that **HPDS BALIKA VIDYA MANDIR RAMANRETI VRINDAVAN MATHURA (U.P.)** Comprises of ground floor/first floor/Second floor floor/Third floor owned/occupied at **RAMANRETI VRINDAVAN MATHURA (U.P.)** has compiled with the Building Bye Laws in accordance with rule of state/UT. And incorporate the provision of building safety as specified in National Building code 2005, School safety policy 2016 and as amended thereafter and has been verified by the officer on **09-02-2026** (date of inspection) in the presence of **Dr. Anjoo Sood** Principal of **HPDS BALIKA VIDYA MANDIR RAMANRETI VRINDAVAN MATHURA (U.P.)**

The Structure of the school building is in good conditon Brick walls are constructed with cement mortar and roofs are of R.C.C slab. All the rooms are well ventilated and airy. Floors are constructed with first class material. School Building falls in seismic Zone-III Structure of scholl building (i.e. foundation, column, bearm, etc.) and that the above said building/premises is safe and fit for running school up to Senior Secondary. The building is made according to safety norms.

[Signature]

अवर अभियन्ता सिविल
नगर निगम मथुरा-वृन्दावन
मथुरा (वृन्दावन)

[Signature]

Principal
Hanuman Prasad Dhanuka
Sarswati Balika Vidya Mandir
Senior Secondary School
Vrindavan